

Locations along Barberry Creek (upstream to downstream)



Fig. 1. Along Dartmouth Street,
7/2003



Fig. 2. Along Greenbelt Walkway
(biological monitoring
station S672), 7/2003




Fig. 3. At Taylor Lane (biological
monitoring station S387), 5/2004



Fig. 4. Below Broadway,
7/2003

Stormflow vs. Baseflow Conditions

Stormflow, 8/13/2004

Baseflow, 8/20/2004



Fig. 5. Along Dartmouth Street



Fig. 6. At S672 (along Greenbelt)



Fig. 7. At S387 (at Taylor Lane)

Selected Problem Conditions



Fig. 8. Railway influence above upstream wetland



Fig. 9. Impaired water quality at outflow of upstream wetland (7/2003)



Fig. 10. Impervious surfaces near stream



Fig. 11. Extensive channelization



Fig. 12. Sedimentation at S672, 5/2004



Fig. 13. Log with growth (bacteria, algae, fungi) at S672, 7/2004